

## **DETAILS OF TAILINGS STORAGE FACILITY**

Tailings Storage Facility (TSF) Name Oryx TSF (BTX4)

**Operation** Beatrix

Operational Status Dormant since mid-2019

Operating Segment RSA - Gold

**Location** Approximately 32 km south-west of the town of Virginia in

the Free State Province – please refer to Figure 1

Latitude, Longitude (decimals) -28.188975, 26.7037361

Ore Source Underground

Type of Storage Facility Impoundment (upstream development)

**Deposition Methodology** Day-Wall Paddock

Year of Commissioning 1981

Consequence Classification (GISTM, 2020) Significant

Operating Contractor Stefanutti Stocks Inland (SSI)

Engineer of Record (EoR) Knight Piesold (Pty) Ltd (KP)

Current Maximum Height (m) 20

Final Maximum Height (m) 20

Total Volume Already Deposited (Mm³) 14,5

Life of TSF (year) N/A















## **TECHNICAL ASPECTS:**

**Design Criteria** 

Stability Assessment and Mitigation Measures

Dam Breach Assessment

Area of Inundation

**Summary of Human Exposure** 

## **DOCUMENTATION:**

Site Specific OMS Manual

Design Basis Report (DBR)

**Environmental Management System** 

GISTM and best practice guidelines including Australian National Committee on Large Dams (ANCOLD) (Guidelines on Tailings Dams, July 2019). Site specific design criteria were specified by the EoR. Details are included in the Design Basis Report (DBR).

A detailed stability assessment based on piezocone probing and some laboratory test work was conducted in 2023 (KP Reference: PR301-00726/36-A Rev A, 3 July 2023).

All the FoS are above the recommended limits and thus no mitigation measures were required.

Construction of a buttress in the west flank due to a localised slip was completed in 2001.

Assessment completed in 2023 (KP Reference: PR301-00726/36-A-PR23-001.

(KP Reference: PR301-00726/36-A-PR23-00154 Rev 0, 28 July 2023

Has been identified by EoRs – please refer to Figure 2

Consequence classification has been based on Population at Risk (PAR). Farmers have been identified and are being engaged through various means.

Version 2023 available

Mandatory Code of Practice (MCOP) document No: 2.3.A-COP is in place (dated June 2019)

Version 2023 available

(KP Reference: RI301-00726/36 Rev A, 27 July 2023)

The Environmental Management System is ISO accredited (ISO 14001:2015)

The initial Environmental Management Programme (EMPr) is dated 2004. Numerous addendums have been submitted with the latest being in 2013.















Surveillance:

**Surveillance Frequency** Daily by the Operator and quarterly reports of critical controls submitted to and reviewed by the EoR

Surveillance Technology/System K2Fly Decipher

**Deformation Monitoring** Interferometric Synthetic Aperture Radar (InSAR)

Phreatic Surface Levels & Pore Pressure Standpipe piezometers Measurements

RISK MANAGEMENT / **EMERGENCY PREPAREDNESS:** 

**Risk Assessment** Annual Risk Assessment (FMEA) completed with no

untoward risk identified

**Risk Management** Site specific OMS Manual

Site specific Trigger Action Response Plans (TARPs) in place

Critical controls established and implemented

Site Specific Emergency Preparedness &

Response Plans (EPRP)

Version 2023 available

Annual emergency mock drill for a catastrophic TSF failure – undertaken on 30 June 2023 with SSW employees and

contractors.

Environmental emergency preparedness is managed on

site according to ISO14001: 2015.

**CLOSURE & POST CLOSURE** 

In place - report prepared by Golder Associates **Closure Planning** (Golder Reference: 20353619-341344-2, April 2021)

**Closure Costing** Adequate financial capacity in place

Financials prepared by Golder Associates

(Golder Reference: 20447293-349381-4, December 2021)

**Asset Insurance Cover** In place - July 2023 to June 2024















## **Independent Reviews:**

Independent Tailings Review Board (ITRB) 4 July 2023 with no material concerns identified

Future ITRB Review 2024

Performance Reviews Annual and quarterly reports with inspections completed

bv EoF

(KP Reference: RI301-00726/38 Rev 0, 3 May 2023)

Dam Safety Review (DSR) Carried out by an independent third party in 2019/2020

with no material findings

(KP Reference: 301-00840/02-010 Rev 1, February 2020)

Next review scheduled for 2024
















Figure 1: Layout of Oryx TSF




Figure 2: Consolidated View of Rainy-Day Scenarios Area of Inundations











